

Mubea™ Ironworkers

| Model | Punch | Die |
|------------|-------|-----|
| 0 | H1 | H1 |
| 48-4 | H1 | H1 |
| 50-4 | H1 | H1 |
| 71-5 | H1 | H1 |
| 88-6 | H1 | H1 |
| 110-7 | H2 | H2 |
| 143 | H2 | H2 |
| 143-8 | H2 | H2 |
| 350 | BF10 | H1 |
| 350E | H1 | H1 |
| 450 | H1 | H1 |
| 500 | H1 | H1 |
| 550 | H1 | H1 |
| 560 | H1 | H1 |
| 600 | H1 | H1 |
| 700 | H1 | H1 |
| 750 | H1 | H1 |
| 800 | H1 | H1 |
| 900 | H2 | H2 |
| 900 | H2 | H2 |
| 1100 | H2 | H2 |
| 1300 | H2 | H2 |
| BF10 | BF10 | H1 |
| BFL 350 | H1 | H1 |
| BFLH 400 | H1 | H1 |
| Bulldog 65 | H1 | H2 |
| HIW 450 | H1 | H1 |
| HIW 1000 | H2 | H2 |
| HIW 1000 | H2 | H2 |
| HP 450 | H1 | H1 |
| HPS 250 | H1 | H1 |
| HPSN 350 | H1 | H1 |
| KBL 0 | H1 | H1 |
| KBL 1/2 | H1 | H1 |
| KBL 1-1/2 | H1 | H1 |
| KBL 3-1/2 | H2 | H2 |
| KBLH 500 | H1 | H1 |
| KBLH 1000 | H2 | H2 |
| KL 33 | H1 | H1 |
| KL 110 | H2 | H2 |
| KLH 500 | H1 | H1 |
| KLH 1000 | H2 | H2 |
| KLS 1100 | H2 | H2 |
| KLSH 550 | H1 | H1 |
| KLSH 1000 | H2 | H2 |
| KLSH 1000 | H2 | H2 |
| MIW 400 | H1 | H1 |
| Profi 500 | H1 | H1 |
| KLSH 550 | H1 | H1 |
| MIW 400 | H1 | H1 |
| Profi 500 | H1 | H1 |

PUNCHES

